

1. According to KKK-A-1822, lateral (right to left) weight distribution must be within \_\_\_\_\_ percentage.

- A. 1
- B. 5
- C. 10
- D. 15

2. Which of the following is the definition of a litter?

- A. an elevating cot
- B. a wheeled cot
- C. a stretcher
- D. a back-board

3. The battery cables have been disconnected on a Ford ambulance. Technician A says: The PCM's (Power Control Module) memory will be temporarily lost. Technician B says: Abnormal transmission shifting may occur for several miles. Who is correct?

- A. Technician A
- B. Technician B
- C. Both A and B
- D. Neither A nor B

4. A 2-way radio system has been installed. The EMS crew reports poor reception. All of the following could be the problem except:

- A. antenna mounted on a non-metallic roof
- B. inadequate ground plane
- C. antenna is trimmed improperly
- D. shielded cable was used

5. According to KKK-A-1822, the preferred method in which the modular body is attached to the frame is:

- A. full floating rubber mounts
- B. u-bolts welded to sub-frame cross members
- C. welding body supports members to frame flanges
- D. bolting body supports through both frame flanges